

|             |                |
|-------------|----------------|
| <b>Type</b> | <b>PS E12B</b> |
| <b>Mast</b> | <b>3600</b>    |

|                    |
|--------------------|
| <b>h3<br/>(mm)</b> |
|                    |
|                    |
|                    |
|                    |
| 3600               |
| 3200               |
| 2900               |
| 2500               |

|               |      |  |
|---------------|------|--|
| <b>Q (kg)</b> |      |  |
|               |      |  |
|               |      |  |
|               |      |  |
|               |      |  |
| 700           | 500  |  |
| 800           | 600  |  |
| 1000          | 800  |  |
| 1200          | 1000 |  |

|              |     |     |  |
|--------------|-----|-----|--|
| <b>c(mm)</b> | 600 | 700 |  |
|--------------|-----|-----|--|

|             |                |
|-------------|----------------|
| <b>Type</b> | <b>PS E12N</b> |
| <b>Mast</b> | <b>3600</b>    |

|                    |
|--------------------|
| <b>h3<br/>(mm)</b> |
|                    |
|                    |
|                    |
|                    |
| 3600               |
| 3200               |
| 2900               |
| 2500               |

|  |               |      |  |
|--|---------------|------|--|
|  | <b>Q (kg)</b> |      |  |
|  |               |      |  |
|  |               |      |  |
|  |               |      |  |
|  |               |      |  |
|  | 700           | 500  |  |
|  | 800           | 600  |  |
|  | 1000          | 800  |  |
|  | 1200          | 1000 |  |

|              |     |     |  |
|--------------|-----|-----|--|
| <b>c(mm)</b> | 600 | 700 |  |
|--------------|-----|-----|--|